

Assisted Living Registry Substantiated Complaint Information

Complaint #: C2021-M67

Name of Residence: New Vision Renaissance Recovery House

Address: 10106 129 Street, Surrey BC

Legal Name of Registrant (Operator): New Vision Supportive Housing Society

The complaint investigation was concluded on January 12, 2022. A summary of the findings of non-compliance(s) with the *Community Care and Assisted Living Act* and/or the Assisted Living Regulation follows. This information is updated as the operator comes into compliance.

All findings are assigned a determination based on the following definitions:

- **In compliance:** meets the requirements of the *Community Care and Assisted Living Act* and/or the Assisted Living Regulation.
- **Not in compliance:** no evidence of meeting the requirements of the *Community Care and Assisted Living Act* and/or the Assisted Living Regulation.

| FINDINGS | | | | |
|--|----------|----------------------------|---|----------------------|
| Section of the Act or Regulation | Category | Date of non- compliance | Date of compliance | Compliance Status |
| Assisted Living Regulation | Housing | November 1, 2021 | December 7, 2021 | In compliance |
| Requirement: Section 17(1)(a): Physical Requirements. A registrant must ensure that the assisted living residence is in a state of good repair and is safe, clean and free of hazards. | | | Compliance Action: The Registrant has provided evidence that repairs have been completed and the mold has been addressed. | |
| Observation: The residence was observed to have broken fixtures, a leaking toilet and evidence of mold. | | | | |

Actions taken or to be taken by Registrant (Operator): The Registrant is required to make repairs, address the mold, and provide evidence of these actions to the investigator.

Actions taken or to be taken by Registry: Continued monitoring through site inspections to ensure physical requirements are in compliance with the Assisted Living Regulation.

Updated August 13, 2021 Page 1 of 1